



Trace elements I

CuSO ₄	7.89	mg
MnSO ₄ x H ₂ O	169.00	mg
ZnSO ₄ x 7 H ₂ O	2.87	g
HCl (10 mM)	100.00	ml

Prepare Trace elements I, flush with nitrogen to make them anoxic, filter-sterilize and store at 4°C